



TETRA COMPACT-X 100 TORQUE / SPEED CHARTS


TETRA COMPACT-X 100 3,2 21




TETRA COMPACT-X 100 3,2 15




TETRA COMPACT-X 100 5.6 15




TETRA COMPACT-X 100 8 15




TETRA COMPACT-X 100 3.2 NO LOAD STARTING



TETRA COMPACT-X 100 5.6 NO LOAD STARTING



TETRA COMPACT-X 100 8 NO LOAD STARTING



- Continuous duty @ 0 ÷ +40°C
- - - Continuous duty @ -40°C
- - - Continuous duty @ +80°C
- 24 Vdc
- 48 Vdc
- 230 Vac
- 400 Vac