

iCS Series Integrated Stepper Motor

iCS series is integrated stepper motor with 14-bit magnetic encoder to solve the loss of step problems in open loop stepper control systems, thus increase system reliability at minimal cost increase. It implements advanced control algorithm of Leadshine based on its tens of years' experience in stepper and servo controls. At very compact size and with all components integrated, the iCS can save mounting space, eliminate encoder connection & motor wiring time, reduce interference, and cut/reduce cable and labor costs.

The iCS series is reliable, affordable and excellent in many industrial applications such as CNC, 3D printer, stage equipment, medical, electronics, packaging...etc.



Feature

- No loss of step & no torque reservation & no hunting or overshooting & no tuning for easy setup
- Enhance performance, especially at low speed application (<60RPM)
- Soft-start with no "jump" when powered on
- Low noise and vibration, smooth motion
- Step&direction and CW&CCW control
- 3 digital inputs, 1 optically isolated digital output
- 14-bit single-turn incremental encoder
- RS232 communication for Leadshine software connection
- Over voltage, over current, position following error protections, etc.



Model Designation

iC	S - <u>17</u> 03 - □
1	Series Name iCS : Integrated closed loop stepper motor
2	Frame Size 17: NEMA17 23: NEMA23 24: NEMA24
3	Holding Torque 03: 0.3N.m 06: 0.6N.m 08: 0.8N.m 13: 1.3N.m 23: 2.3N.m 21: 2.1N.m 31: 3.1N.m 30: 3.0N.m 35: 3.5N.m
4	Remark Blank: Normal type L: Special type


Technical Specification

			Holding		Comm	and Source	Electrica	l Parameters		Co	ontrol Signa	ıl	
Model	Frame Size	Length (mm)	Holding Torque (N.m)	Weight (Kg)	PUL&	CW&CCW	Power Voltage (VDC)	Peak Current (A)	U	U	Max Input Frequency	PUL	MIN DIR Setup
iCS-1703		64	0.3	0.5		X	20-36	0.3 - 3.0				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Setup
iCS-1706	NEMA17	72	0.4	0.9		х	20-36	0.3 - 3.0					
iCS-1708		85	0.8	1.1	\checkmark	X	20-36	0.3 - 3.0					
iCS-2313		75	1.3	1.0	\checkmark	\checkmark	20-50	0.5 - 4.5					
iCS-2323	NEMADO	96	1.9	1.3	\checkmark	\checkmark	20-50	0.5 - 7.0	7-16mA	5V	200KHz	2.5µs	5.0µs
iCS-2321-L	NEMA23	89	2.1	1.4	\checkmark	\checkmark	20-50	0.5 - 7.0					
iCS-2331-L		109	3.1	1.6	\checkmark	\checkmark	20-50	0.5 - 7.0					
iCS-2430	NEMADA	109	3.0	1.6	\checkmark	\checkmark	20-50	0.5 - 7.0					
iCS-2435	NEMA24	122	3.5	1.9	\checkmark	\checkmark	20-50	0.5 - 7.0					




Dimension

(Unit: mm [1inch=25.4mm])



Models	L1 length	L length
iCS-1703	43	64
iCS-1706	51	72
iCS-1708	64	85



φ<u>8</u>-


P-P 2:1

Models	L1 length	L length
iCS-2313	54	75
iCS-2323	75	96
iCS-2321-L	68	89
iCS-2331-L	88	109
iCS-2430 ^①	88	109
iCS-2435 ²	101	122

Note: ① Frame size is 60mm, center diameter is 36mm.
② Frame size is 60mm, center diameter is 36mm, shaft diameter is 10mm



Connector and Pin Assignment



Pin Assignments of P1

PIN	I/O	Details				
		Power supply positive connection.				
VCC	I	iCS-17xx:20-36VDC				
		iCS-23xx and iCS-24xx: 20-50 VDC				
GND	Ι	Power supply ground connection.				
ALM-	0	A larmy An OC output signal. It takes a sinking or sourcing at 5 $24W@20mA$				
ALM+	0	<u>Alarm:</u> An OC output signal. It takes a sinking or sourcing at 5-24V@30mA				
ENA-	Ι	Enable Signals: Optional, not connected by default.				
TINIA .	т	(1) Effective high level is 4.5-5V; Effective low level is 0-0.5V connection				
ENA+	I	(2) ENA signal requires advance DIR signal minimum 200ms in single pulse mode				
DIR-	I	Pulse and Direction Connection:				
DIR+	Ι	(1) Optically isolated, high level 4.5-5V, low voltage 0-0.5V.				
PUL-	I	 (2) Max 200 KHz input frequency. (3) The width of PUL signal is at least 2.5µs, duty cycle is recommended 50%. 				
101-	-	(4) Single pulse (step & direction), iCS-23xx and iCS-24xx support double pulse				
PUL+	I	(CW&CCW), while iCS-17xx do not support.				
		(5) DIR signal requires advance PUL signal minimum 5 μ s.				

Notes:

(1) Shielding control signal wires is suggested;

(2) To avoid/reduce interference, do not tie control signal cables and power wires together.

> Tuning Port P2

The P2 connector is a RS232 communication port for Leadshine software connection. It is just used to modify parameter, not for equipment control because neither precision nor stability is sufficient. If you need a Modbus-RS485 control, use a Leadshine iEM-RS series integrated stepper motor. The interface definition is as follows:







Figure 5: RS232 Tuning Port

> DIP Switch Configurations

The iCS series has a row of DIP switches, but the iCS17xx and iCS-23xx DIP switches are a bit different, as follows



• For iCS-17xx Series

Microstep resolution is set by SW1, 2, 3, 4 of the DIP switches as shown in the following table:

Steps/Revolution	SW1	SW2	SW3	SW4
200 (Default)	on	on	on	on
400	off	on	on	on
800	on	off	on	on
1600	off	off	on	on
3200	on	on	off	on
6400	off	on	off	on
12800	on	off	off	on
25600	off	off	off	on
1000	on	on	on	off
2000	off	on	on	off
4000	on	off	on	off
5000	off	off	on	off
8000	on	on	off	off
10000	off	on	off	off
20000	on	off	off	off
25000	off	off	off	off

• For iCS-23xx and iCS-24xx Series

Steps/Revolution	SW1	SW2	SW3	SW4

www.leadshine.com



Datasheet of iCS Series Integrated Stepper Motor

et of feb beries integrated biepper motor				
400 (Default)	on	on	on	on
800	off	on	on	on
1600	on	off	on	on
3200	off	off	on	on
6400	on	on	off	on
12800	off	on	off	on
25600	on	off	off	on
51200	off	off	off	on
1000	on	on	on	off
2000	off	on	on	off
4000	on	off	on	off
5000	off	off	on	off
8000	on	on	off	off
10000	off	on	off	off
20000	on	off	off	off
40000	off	off	off	off

> Other DIP Switch Settings

• For iCS-17xx Series (SW5-SW6)

	Function	On	Off
SW5	Default Direction	CW (clockwise)	CCW (counterclockwise)
SW6	Closed/Open loop	Open Loop	Closed Loop

• For iCS-23xx and iCS-24xx Series (SW5-SW8)


	Function	On	Off
SW5	Default Direction	CW (clockwise)	CCW (counterclockwise)
SW6	Pulse Mode	CW&CCW	PUL&DIR
SW7	Smoothing Time	Enable	Disable
SW8	Closed/Open Loop	Open Loop	Closed Loop

Wiring

The iCS series motor can accept differential and single-ended control signal inputs (open-collector and PNP output). It has 3 optically isolated control inputs, PUL, DIR, and ENA. Refer to the following two figures for connections of PNP and NPN signals.



Datasheet of iCS Series Integrated Stepper Motor



Connections to Differential signals