



The curve of torque-speed

Speed (r/min)	Torque (N.m)	Operating Zone
0	3.18	Continuous Duty Zone
3000	3.18	Continuous Duty Zone / Intermittent Duty Zone boundary
3000	9.54	Intermittent Duty Zone
5000	6.36	Intermittent Duty Zone

80mm,high inertia,1000w servo motor
23bit magnetic encoder, no brake