





MOTOROLLER 76 FRAMELESS DIMENSIONS

Motoroller 76 100



Dimensions in mm



POWER CONNECTOR Hypertac 6p MS

- 1 = -
- 2 = PHASE U
- 3 = PHASE V
- 4 = PHASE W
- 5 = -
- 6 = PE



SIGNAL CONNECTOR M12 5p MS

- 1 = HALL U
- 2 = HALL V
- 3 = HALL W
- 4 = 5V
- 5 = GND

